

Test and Calibration — Continued

Bench Integrated EBP Touch Tester



- Simply 'Touch to Test' on demand tester
- Can be mounted flush in bench trunking or bench top
- 240V mains powered and earthed
- Test Voltage is 16V
- Pass range: 0.75 to 35MΩ ±6%
- Red LED indicates fail, green LED and buzzer indicate pass
- Function test button
- Front plate: 86 86mm
- Lead is 1 metre long



STA121

Mfrs. List No.	Order Code	1+	5+	10+	Price Each
Mains Plug H540	302-6826				
Schuko Euro Plug H540EU	322-4806				
Standard Calibration Charge		S		Each	

Portable EBP Tester



- Provides Earth Bonding Point and wrist strap tester in one block
- Simply 'Touch to Test' on demand tester
- Operators connected to another EBP in proximity of the instrument can test too
- For bench top or front mounting
- Uses an external power supply
- 5V test voltage
- Pass range: 0.75 to 35MΩ
- Conforms to IEC 61340-5-1
- Red LED indicates fail, green LED and buzzer indicate pass



● Supplied with mounting screws, power supply, and calibration certificate

This unique instrument provides an EBP with two 10mm snap fastener connections and a tester in one block, and is to be mounted in a convenient place on the operator workstation. Path to ground can also be tested with this instrument. It can be calibrated using Order Code 595-962 calibration box.

STA122

Mfrs. List No.	Order Code	1+	5+	10+	Price Each
Mains Plug H580	302-6814				
Schuko Euro Plug H580EU	322-4790				
Standard Calibration Charge		S		Each	

Wrist Band and Earth Tester



- Simple, easy-to-use earth tester
- Plugs directly into 13A mains sockets
- Gives audible and visual warning of discontinuity between operator, wrist band and ground cord
- Tests mains socket for incorrect polarity
- 'High-Fail' set at 35MΩ, 'Low Fail' at 750kΩ
- 4mm and 10mm press studs, and 4mm banana sockets fitted



H = 92, W = 50, D = 85 (inc. pins)

STA66

Mfrs. List No.	Order Code	1+	5+	20+	Price Each
FSK-UK-2	557-754				
Standard Calibration Charge		S		Each	

Wrist Strap Tester



- Compact
- Simple to operate
- LED indication of pass/fail
- Pass range <10MΩ and 750kΩ
- Accepts standard/shrouded banana plugs, and 10mm studs
- Low battery indication
- Supplied with Dual Lock Wall Mounting Kit, battery and instructions
- 746 incorporates a.c. power supply input



H = 32, W = 95, D = 62.5

STA95

Mfrs. List No.	Order Code	1+	5+	10+	Price Each
Wrist Strap Tester 745	997-134†				
Wrist Strap Tester with PSU 746	335-8355				
Standard Calibration Charge		S		Each	

† Available until stocks are exhausted

Static Sensor



- Measures static voltages on objects and surfaces
- Lightweight hand-held unit
- Accurate LCD display
- 0-1990V and 0-19.9kV ranges
- 2 output jacks for remote monitoring/recording
- Battery level check facility
- Supplied with 9V battery and operating instructions



H = 41, W = 67, D = 111

STA68

Mfrs. List No.	Order Code	1+	3+	5+	Price Each
709	681-453				
Standard Calibration Charge		S		Each	

Static Field Meter



- Locates and measures static charges
- Accurate LED display, 0 to ±1999V per inch
- Compact, hand-held design
- 'Sample' and 'Hold' reading feature
- Low battery indicator
- Supplied with isolated plate fixture, lightweight ground card, battery and full operating instructions



H = 33, W = 61, D = 107

STA69

Mfrs. List No.	Order Code	1+	3+	5+	Price Each
713	681-441				
Standard Calibration Charge		S		Each	

Portable 100V Test Kit



- Includes H700 tester, one H7007 probe and one HA108 concentric ring probe and leads
- Handy carry case lined with anti-static foam
- Used to measure R_S and R_G of bench and floor surfaces
- Supplied with calibration certificate

This kit provides the necessary equipment required to ensure compliance of the EPA's. It comprises instruments and accessories in a handy carry case.

STA126

Please Call our Sales Office