
## Farnell Tools – Hand & Workholding



'D' connector	punches to	greatly simplify	/ the task of	producing this	complex shape
The start start	and the second s	a design of a second free second	In a Later Statistical	a state of the state of the	

The tool also punches the two mounting holes in the same operation
It is essential to use the appropriate stripping tool

For 9 and 15 way use stripper Order Code 149-391 on **page 1778**. For 25 to 50 way use stripper Order Code 149-392 on **page 1778**.

elping Hand			ces		DURAT	00L
50 ways front	.14	9-412				
25 ways front 25 ways rear		9-408 9-409				
15 ways rear	.14	9-407				
9 ways rear 15 ways front		9-405 9-406				
9 ways front		9-404	1+	5+	5+	
	Orde	er Code	1+	Price Ea 3+	ach 5+	
50 ways front	57.4	15.7	61.1	908-0050	149-412	199
25 ways front 25 ways rear	43.4 41.9	12.9 11.3	47.0 47.0	908-0030 909-0030	149-408 149-409	
15 ways rear	28.2	11.3	33.3	909-0020	149-407	
9 ways rear 15 ways front	19.8 29.6	11.3	25.0 33.3	909-0010 908-0020	149-405 149-406	
9 ways front	A 21.3	B 12.9	C 25.0	List No. 908-0010	Order Code 149-404	

 Allows a PCB or any delicate or small work item to be held in position using the two crocodile clips

The user can keep both hands free for positioning, soldering and assembling

200X

				TEE444
Order Code 312-5350	1+	Price Each 5+	10+	

The following vice/clamping tools are a multi purpose system based around the universal swivel ball joint units into which may be fitted either vices or the central mounting rod. A mini-vice swivel joint and a variety of clamps may be added to the rod in any configuration required. All moulded parts are glass filled nylon.

## **Bench Bases**



- Universal swivel ball joints with mountings for bench top (143-899) or bench clamp (143-900)
- The swivel joint is lockable in any position
- The bases will accept either the long or the short vice or the multi purpose clamping system mounting rod

		Price Each			
Bench top base 'G' clamp base	Order Code .143-899 .143-900	1+	4+	20+	

**1780** Tools – Hand & Workholding